

[illegible]

2/16

FIG. 2A






FIG. 2B

3/16

FIG. 3A



4/16




FIG. 3B




FIG. 3C

5/16

FIG. 3D






FIG. 3E



6/16

FIG. 4A



7/16

FIG. 4B





FIG. 4C



8/16




FIG. 6A





FIG. 6B





9/16

FIG. 7A









FIG. 7B




10/16



11/16

FIG. 9



0

FIG. 10





FIG. 11



12/16

FIG. 12




FIG. 13

COLUMNS		A	B	C	D	
ROWS	1	16	13	11	1,17	300
	2	3	6	8	14	
	3	12	10	2,18	5	310
	4	7	4	15	9	

310

13/16

FIG. 14




FIG. 15





FIG. 16



15/16

FIG. 17A





FIG. 17B



16/16

FIG. 18




FIG. 19

